



Jumper on (make BUF_SEL to GND)
to disable the I2C buffer between U2 and M2 SMBus)

GND	BUF_SEL
U2_CLKREQ#	M2_DEVSLP
U2_ACTIVITY#	M2_ACTIVITY#
U2_PRSENT#	M2_PRSENT#
U2_IFDET#	M2_IFDET#
U2_SPCIERST	M2_PERST#
U2_PERST#	M2_PERST#
U2_CLKREQ#	M2_CLKREQ#
U2_WAKE#	M2_WAKE#